

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,864,569 B2  
DATED : March 8, 2005  
INVENTOR(S) : Paul Evans

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10,

Line 41, "a set or pins" should read as -- a set of pins --.

Line 58, "conductive trucks" should read as -- conductive tracks --.

Line 67, "set or topside circuit components." should read as -- set of topside circuit components. --.

Column 13,

Line 12, "a multiplexer" should read as -- a multiplexor --.

Signed and Sealed this

Twenty-fifth Day of October, 2005

A handwritten signature in black ink, appearing to read "Jon W. Dudas". The signature is stylized with a large, looped initial "J" and a cursive "Dudas".

JON W. DUDAS  
*Director of the United States Patent and Trademark Office*